



Ø108 PISTON COMBUSTION CHAMBER & CLEARANCES
(MODEL :9210,9214,9219,9224,9234,9239,11012,11025)



Compression
Ring Gap

1. Firing Ring Gap : 0.40 - 0.65 mm.
2. Rectangular Ring Gap : 0.40 - 0.65 mm.
3. Chin Type Ring Gap : 0.40 - 0.65 mm.
4. Double Chamfer Type Oil Ring Gap : 0.30 - 0.60 mm.